



SAFETY WORK ORDERS



PRI	WORKORDE R#	DATE	MSC	Type Structure	BLDG#	DESCRIPTION OF REQUEST
1	4I000465P	31-Jan-05	4 BCT	Dining Facility	12007	Replace floor in kitchen
2	4I002134P	06-Jul-04	2 BCT	Motor pool	9122	Replace fire doors
3	4I001454P	14-May-04	4 BCT	Motor pool	11012	Install exhaust ventillation system in 11012
4	4I002404P	29-Jul-04	STB	Admin	10040	Remove lead based paint from building
5	4I002144P	06-Jul-04	2 BCT	Motor pool	9122	Replace stairs
6	4I002154P	6-Jul-04	2 BCT	Motor pool	9122	Install concrete pads for fuel trucks
7	4I000944P	06-Apr-04	2 BCT	Motor pool	17048	Install 220 outlet x5 and 110 outlets x12 between two offices
8	4I002104P	6-Jul-04	2 BCT	Motor pool	9122	Replace exhaust tubes
	4I000864P	04-Feb-04	AVN BDE	Airfield Hangars	7022	Put fire rated insulation throughout walls around piping
	4I000124P	4-Feb-04	AVN BDE	Airfield Hangars	7022	Fire doors throughout building need bottom seal & panic hardware
	4I001414P	13-May-03	2 BCT	Motor pool	17048	Install grounding system
	4I002044P	30-Jun-04	2 BCT	Motor pool	9535	Install grounding rods
	4I002074P	06-Jul-04	AVN BDE	Motor pool	6951	Repair roof
	4I002364P	22-Jul-04	STB	Admin	10043	Repair chaplins roof Service order section attempted repair and cannot fix
	4I002814P	02-Aug-04	4 BCT	Admin	11006, 11007 11008, 11009	Install exhaust ventillation system
	4I002984P	10-Aug-04	AVN BDE	Motor pool	7021	Install Safety Equipment
	4I003004P	11-Aug-04	STB	Admin	410	Install Circuits



SAFETY WORK ORDERS



PRI	WORKORDE R#	DATE	MSC	Type Structure	BLDG#	DESCRIPTION OF REQUEST
	4I003304P	15-Sep-04	STB	Parking Lot	410	Install two pedestrian crossing signs across 761st St.
	4I003334P	21-Sep-04	AVN BDE	Dining Facility	87017	Install fire suppression system
	4I003354P	21-Sep-04	AVN BDE	Admin	87003	Install fire suppression system
	4I003364P	21-Sep-04	AVN BDE	Airfield Hangars	7007	Install exit lights throughout building
	4I003554P	27-Sep-04	2 BCT	Motor pool	9127	Paint & repair building; remove stairs etc.
	4I003874P	20-Oct-04	AVN BDE	Airfield Hangars	6940	Install 5+ outlets in BN q/c shop
	4I003884P	20-Oct-04	AVN BDE	Airfield Hangars	6940	Replace plexiglass on 2nd flr window w/fire safety glass
	4I004024P	27-Oct-04	4 BCT	Admin	10015	Install lighting in basement stairwell
	4I000345P	05-Jan-05	1-44 ADA	Admin	10016, 10018	Adhere vinyl tiles to floor
	4I000355P	05-Jan-05	FIRES	Admin	87010 (starker gym)	Repair basketball goal hanging from frame
	4I000445P	21-Jan-05	4 BCT	Admin	10015	Emergency lights
	4I000745P	09-Mar-05	AVN BDE	Admin	9576	Construct speed bumps
	4I000755P	09-Mar-05	AVN BDE	Admin	6940	Construct speed bumps
	4I000775P	09-Mar-05	AVN BDE	Admin	870021	1/2 truck load of dirt to level low spot
	4I000825P	11-Mar-05	4 BCT	Admin	10015	Construction of clearing barrels
	4I000925P	29-Mar-05	AVN BDE	Admin	6940	Window replacement

DINING FACILITY WORK ORDERS

PRI	WORKORDER#	DATE	MSC	Type Structure	BLDG#	DESCRIPTION OF REQUEST	CATEGORY
1	4I000465P	31-Jan-05	4 BCT	Dining Facility	12007	Replace floor in kitchen	Safety
	4I003334P	21-Sep-04	AVN BDE	Dining Facility	87017	Install fire suppression system	Safety
	4I003294P	15-Sep-04	2 BCT	Dining Facility	9205	Rekey all doors interior & exterior	Security
	4I003024P	16-Aug-04	4 BCT	Dining Facility	12007	Install 220 Volt Outlet	Operations
	4I002834P	04-Aug-04	4 BCT	Dining Facility	12007	Disconnect utility table/water drain pipes from floor	Operations
	4I002844P	04-Aug-04	4 BCT	Dining Facility	12007	Modify utility table- cut hole into table and install hot bar into table	Operations
	4I002864P	04-Aug-04	4 BCT	Dining Facility	12007	Install 220v outlet into outside serving line area to provide power to utility table components	Operations
	4I002874P	04-Aug-04	4 BCT	Dining Facility	12007	Electrical modifications to utility table	Operations
	4I002934P	09-Aug-04	4 BCT	Dining Facility	12007	Install wheels onto freezer #4 & relocate freezer (electrical work involved)	Operations
	4I002944P	09-Aug-04	4 BCT	Dining Facility	12007	Remove legs on refrigerator and attach wheels (electrical work involved)	Operations
	4I002954P	09-Aug-04	4 BCT	Dining Facility	12007	Remove legs on reach in freezer #5, attach wheels (electrical work involved)	Operations
	4I002394P	27-Jul-04	1 BCT	Dining Facility	12005	Install TV stands	Operations

DINING FACILITY WORK ORDERS

PRI	WORKORDER#	DATE	MSC	Type Structure	BLDG#	DESCRIPTION OF REQUEST	CATEGORY
	4I003104P	27-Aug-04	1 BCT	Dining Facility	12005	Install a clerks door in ration room	Operations
	4I003114P	27-Aug-04	1 BCT	Dining Facility	12005	Door needs to be replaced	Operations
	4I003324P	21-Sep-04	AVN BDE	Dining Facility	87017	Repair roof leaks over several areas of building	Operations
	4I003684P	30-Sep-04	1 BCT	Dining Facility	12005	Install outlet for ice cream machine	Operations
	4I003694P	30-Sep-04	1 BCT	Dining Facility	12005	Install plexiglass in front of grills	Operations
	4I003704P	30-Sep-04	1 BCT	Dining Facility	12005	Install gas line for grill (parts on hand)	Operations
	4I003784P	14-Oct-04	AVN BDE	Dining Facility	87017	Remodel dining facility	Operations
	4I003934P	21-Oct-04	4 BCT	Dining Facility	12007	Remove blue paint on entrance steps, parking spaces, and curbs	Operations
	4I000015P	08-Nov-04	AVN BDE	Dining Facility	87017	Replace electric breaker boxes in kitchen	Operations
	4I000025P	08-Nov-04	AVN BDE	Dining Facility	87017	Add gas line on short order line	Operations
	4I000035P	08-Nov-04	AVN BDE	Dining Facility	87017	Retile dining area	Operations
	4I000475P	31-Jan-05	4 BCT	Dining Facility	12007	Slab needs to be placed in walk way	Operations



Dining Facilities



- **DOL inspected all 4ID Dining Facilities on 11 January and 23 March.**
 - Raider DFAC, DISCOM DFAC, Roosevelt DFAC, and Aviation DFAC
 - Equipment found to be in good repair.
 - Need to place concrete pads for walk-in units at BLDG 12007 (Work Order submitted 27 Jan 05, 4I000475P)
- **DIVEN/DPW inspected all 4ID Dining Facilities on 26 January.**
 - Validated Safety Work Orders
 - DPW developed cost estimate for replacement of floor in DISCOM DFAC, 4th UA's DFAC, on 10 Feb. (Cost exceeded \$2500 credit card limit)
 - DPW proposed using skid resistant strips on 22 Feb. They were found to be unsanitary.
 - Currently working other funding options through Garrison and DPW to get the floor repaired immediately.